



Product Data Sheet

G1100 - Superior Gripper Grab

DESCRIPTION

Spartan G1100 is a liquid PU adhesive suitable for bonding most timbers, metal trims to absorbent surfaces and many other types of products.

DIRECTIONS FOR USE

All surfaces must be clean & free of dust.

Apply a thin bead of G1100 to one surface.

Press the two surfaces together. Apply pressure, use fixing nails or screws or clamp to keep two surfaces in contact while adhesive cures.

Large extrusions should also be secured with appropriate fixing screws.

CURING TIME

G1100 deploys a moisture cure system. Allow approx. 1 hour curing time depending on application. This process may be accelerated by spraying a light mist of water to one of the surfaces. Thick beads will take longer to cure and will have a weaker bond than a thinner bead. The thicker the bead of G1100 the more the product will tend to foam.

CLEAN UP

Clean tools immediately after use with suitable solvent cleaner.

Note: Always carry out your own site test to confirm suitability of this product with your application. Additional information on physical properties, health hazards, storage, handling, and transport is available in the Safety Data Sheet (SDS), available on request.

KEVMOR
TRADE SUPPLIES
www.kevmor.com.au

Kevmor Trade Supplies

11 Belmont Avenue, Belmont WA 6104

P: 08 9277 7177

E: sales@kevmor.com.au