

Job Name: Mrs Ellie H Stephens
Date and Time: 9-10-19 11:32 AM
Name of Structure: Mock Testing House
Address of Structure: 45 Nimm Street, Clarkson WA
Name of Testing Person: John Doe
Title of Testing Person: Moisture Tester for CPF
Affiliation: Employee
Address of Testing Company: 121 Alpine Road, Bayswater WA

Floor	Test Location	Date of Test	Sensor Serial Number	Depth of Hole F	Relative Humidity in	Temperature in Concrete, C	Air Relative Humidity, %	Air Temperature, C
Living Room	Probe 1	07/01/2019 08:44	050821B30000	3.8	56.4	21.9	57.6	18.4
Living Room	Probe 1	07/01/2019 08:51	050821B30000	3.8	68.6	18.8	58.5	17.9
Living Room	Probe 1	07/01/2019 12:04	050821B30000	3.8	92.7	14.6	51.5	23.2
Living Room	Probe 1	07/02/2019 08:46	050821B30000	3.8	96.9	12.1	50.2	18
Living Room	Probe 1	07/02/2019 09:19	050821B30000	3.8	97.2	12.1	60.2	16.1
Living Room	Probe 1	07/02/2019 02:22	050821B30000	3.8	97.2	14	49.4	23.1
Living Room	Probe 1	07/03/2019 07:46	050821B30000	3.8	98.3	12.1	57.1	13.6
Living Room	Probe 1	07/04/2019 11:56	050821B30000	3.8	98	15.3	66.6	16.9
Living Room	Probe 1	07/23/2019 02:57	050821B30000	3.8	100	15.2	49	22.6
Living Room	Probe 1	07/23/2019 02:58	050821B30000	3.8	99.5	15.4	50.8	22.5
Theatre Room	Probe 2	07/02/2019 02:18	50843790000	3.8	78	15.7	53.7	21.1
Theatre Room	Probe 2	07/02/2019 02:19	50843790000	3.8	77.3	16.1	47.6	22.1
Theatre Room	Probe 2	07/03/2019 07:44	50843790000	3.8	82.4	11.9	61.3	9.3
Theatre Room	Probe 2	07/03/2019 11:18	50843790000	3.8	80.2	13.7	56.8	16.7
Theatre Room	Probe 2	07/03/2019 07:05	50843790000	3.8	80	16.3	51.7	17.2
Theatre Room	Probe 2	07/03/2019 07:06	50843790000	3.8	79.6	16.4	49.5	19.1
Theatre Room	Probe 2	07/04/2019 11:56	50843790000	3.8	81	16.3	63.3	18.4
Theatre Room	Probe 2	07/23/2019 02:59	50843790000	3.8	86.8	14.4	50.8	22.5